# Uniform Appraisal Dataset Definitions

File No. 1004 UAD

### Condition Ratings and Definitions

C1 The improvements have been very recently constructed and have not previously been occupied. The entire structure and all components are new and the dwelling features no physical depreciation.\*

"Note: Newly constructed improvements that feature recycled materials and/or components can be considered new dwellings provided that the dwelling is placed on a 100% new foundation and the recycled materials and the recycled components have been rehabilitated/re-manufactured into like-new condition. Recently constructed improvements that have not been previously occupied are not considered "new" if they have any significant physical depreciation (i.e., newly constructed dwellings that have been vacant for an extended period of time without adequate maintenance or upkeep).

- C2 The improvements feature no deferred maintenance, little or no physical depreciation, and require no repairs. Virtually all building components are new or have been recently repaired, refinished, or rehabilitated. All outdated components and finishes have been updated and/or replaced with components that meet current standards. Dwellings in this category either are almost new or have been recently completely renovated and are similar in condition to new construction.
- C3 The improvements are well maintained and feature limited physical depreciation due to normal wear and tear. Some components, but not every major building component, may be updated or recently rehabilitated. The structure has been well maintained.
- C4 The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear. The dwelling has been adequately maintained and requires only minimal repairs to building components/mechanical systems and cosmetic repairs. All major building components have been adequately maintained and are functionally adequate.
- C5 The improvements feature obvious deferred maintenance and are in need of some significant repairs. Some building components need repairs, rehabilitation, or updating. The functional utility and overall livability is somewhat diminished due to condition, but the dwelling remains useable and functional as a residence.
- C6 The improvements have substantial damage or deferred maintenance with deficiencies or defects that are severe enough to affect the safety, soundness, or structural integrity of the improvements. The improvements are in need of substantial repairs and rehabilitation, including many or most major components.

### **Quality Ratings and Definitions**

- Q1 Dwellings with this quality rating are usually unique structures that are individually designed by an architect for a specified user. Such residences typically are constructed from detailed architectural plans and specifications and feature an exceptionally high level of workmanship and exceptionally high-grade materials throughout the interior and exterior of the structure. The design features exceptionally high-quality exterior refinements and ornamentation, and exceptionally high-quality interior refinements. The workmanship, materials, and finishes throughout the dwelling are of exceptionally high quality.
- Q2 Dwellings with this quality rating are often custom designed for construction on an individual property owner's site. However, dwellings in this quality grade are also found in high-quality tract developments featuring residences constructed from individual plans or from highly modified or upgraded plans. The design features detailed, high-quality exterior ornamentation, high-quality interior refinements, and detail. The workmanship, materials, and finishes throughout the dwelling are generally of high or very high quality.
- Q3 Dwellings with this quality rating are residences of higher quality built from individual or readily available designer plans in above-standard residential tract developments or on an individual property owner's site. The design includes significant exterior ornamentation and interiors that are well finished. The workmanship exceeds acceptable standards and many materials and finishes throughout the dwelling have been upgraded from "stock" standards.
- Q4 Dwellings with this quality rating meet or exceed the requirements of applicable building codes. Standard or modified standard building plans are utilized and the design includes adequate fenestration and some exterior ornamentation and interior refinements. Materials, workmanship, finish, and equipment are of stock or builder grade and may feature some upgrades.
- Q5 Dwellings with this quality rating feature economy of construction and basic functionality as main considerations. Such dwellings feature a plain design using readily available or basic floor plans featuring minimal fenestration and basic finishes with minimal exterior ornamentation and limited interior detail. These dwellings meet minimum building codes and are constructed with inexpensive, stock materials with limited refinements and upgrades.
- Q6 Dwellings with this quality rating are of basic quality and lower cost; some may not be suitable for year-round occupancy. Such dwellings are often built with simple plans or without plans, often utilizing the lowest quality building materials. Such dwellings are often built or expanded by persons who are professionally unskilled or possess only minimal construction skills. Electrical, plumbing, and other mechanical systems and equipment may be minimal or non-existent. Older dwellings may feature one or more substandard or non-conforming additions to the original structure.

### **Treatment Of Bathroom Counts**

For purposes of this report, in the Improvements Section, Finished Rooms Above Grade, the count of bathrooms is represented as the number of "full" bathrooms to the left of the period and the count of "half" bathrooms to the right of the period. A three-quarter bath is counted as a full bath. Quarter baths (baths that feature only a toilet) are not included in the bathroom count.

## Abbreviations Used in Data Standardization Text

Abbrev.	Full Name	Appropriate Fields	Abbrev.	Full Name	Appropriate Fields
ac	Acres	Area, Site	Mtn	Mountain View	View
AdjPrk	Adjacent to Park	Location	N	Neutral	Location & View
AdjPwr	Adjacent to Power Lines	Location	NonArm	Non-Arms Length Sale	Sale or Financing Concessions
Α	Adverse	Location & View	BsyRd	Busy Road	Location
ArmLth	Arms Length Sale	Sale or Financing Concessions	0	Other	Basement & Finished Rooms Below Grade
ba	Bathroom(s)	Basement & Finished Rooms Below Grade	Prk	Park View	View
br	Bedroom	Basement & Finished Rooms Below Grade	Pstrl	Pastoral View	View
В	Beneficial	Location & View	PwrLn	Power Lines	View
Cash	Cash	Sale or Financing Concessions	PubTrn	Public Transportation	Location
CtySky	City View Skyline View	View	r	Recreational (Rec) Room	Basement & Finished Rooms Below Grade
CtyStr	City Street View	View	Relo	Relocation Sale	Sale or Financing Concessions
Comm	Commercial Influence	Location	REO	REO Sale	Sale or Financing Concessions
С	Contracted Date	Date of Sale/Time	Res	Residential	Location & View
Conv	Conventional	Sale or Financing Concessions	RH	USDA -Rural Housing	Sale or Financing Concessions
CrtOrd	Court Ordered Sale	Sale or Financing Concessions	s	Settlement Date	Date of Sale/Time
DOM	Days On Market	Data Sources	Short	Short Sale	Sale or Financing Concessions
e	Expiration Date	Date of Sale/Time	sf	Square Feet	Area, Site, Basement
Estate	Estate Sale	Sale or Financing Concessions	Unk	Unknown	Date of Sale/Time
FHA	Federal Housing Authority	Sale or Financing Concessions	VA	Veterans Administration	Sale or Financing Concessions
GlfCse	Golf Course	Location	w	Withdrawn Date	Date of Sale/Time
Glfvw	Golf Course View	View	wo	Walk Out Basement	Basement & Finished Rooms Below Grade
Ind	Industrial	Location & View	wu	Walk Up Basement	Basement & Finished Rooms Below Grade
in	Interior Only Stairs	Basement & Finished Rooms Below Grade	WtrFr	Water Frontage	Location
Lndfl	Landfill	Location	Wtr	Water View	View
LtdSght	Limited Sight	View	Woods	Woods View	View
Listing	Listing	Sale or Financing Concessions			
1		-	1		